


Power Brake Exchange

260 Phelan Ave. San Jose, Ca. 95112 Ph. (408) 292-1305 Fax (408) 294-6817
Technical Bulletin – TB8

Ford Rack & Pinion Pressure-Return Port: Which is Which?

- TYPE:** Ford rack & pinion units with same size pressure and return ports.
- PROBLEM:** Because ports are the same thread size, the pressure and return hoses can be reversed, causing violent self-steering and damage to the rack.
- FIX:** Use figures below to determine the pressure port for your part number.



Note: The original rack & pinion may have a removable check valve in the pressure port. Transfer the check valve to the replacement unit. Use the figures above to determine the correct port for the check valve.